


PROPERTY INSPECTIONS, LLC

(480) 635-6404 www.amerigo-llc.com troy@amerigo-llc.com Inspected By: Troy Bashford #58611



Home Inspection Report

Prepared For:

Elizabeth & Travis Garcia

Property Address:

4444 E. Mendocino Dr. Chandler, AZ 85286

Inspected on Wed, Feb 12 2020 at 7:28 AM

Table of Contents

Report Summary	4
General	10
Site	10
Exterior	11
Garage	11
Roofing	12
Structure	12
Interior	13
Bedrooms	16
Bathrooms	22
Kitchen	28
Laundry	30
Plumbing	32
HVAC	35
Electrical	43
Pool/Spa	47

Thank you for the opportunity to conduct a home inspection of the property listed above. The purpose of the inspection and report are to describe the major systems and components of the home, and to identify any such system or component that is in need of immediate major repair. The inspection and report should help you better understand the types of systems that are part of the home and their condition. The inspection and the report are intended to meet the Arizona Standards of Professional Practice, as interpreted by the inspector.

The report should be read in its entirety. In addition to the checklist items included in the report there are several comments which are meant to help you further understand certain conditions observed. These are easy to find by looking for their icons along the left side margin. Comments with the blue icon are primarily informational and comments with the orange icon are also displayed on the summary. Please read them all.

DEFINITION OF CONDITION TERMS

Satisfactory: At the time of inspection and after visual observation of the component, there was no visible indication of a major defect that was in need of immediate repair. When and if the component was operated, it did operate and appeared to function normally. A satisfactory condition does not mean the component or system is in perfect, near perfect, or new condition.

Marginal: At the time of inspection the component is functioning but is estimated to be nearing the end of its useful life. Operational maintenance and continued observation are recommended. Replacement anticipated.

Repair or Replace: At the time of inspection the component does not function as intended or presents a Safety Hazard. Repair or replacement is recommended.

Further Evaluation: The component requires further technical or invasive evaluation by qualified professional tradesman or service technician to determine the nature of any potential defect, the corrective action and any associated cost.

At the discretion of the inspector other terms may be used to help better describe the conditions. If there are questions regarding any condition please contact your inspector.

Any and all repairs, replacements, and or further evaluations that are recommended or required should be performed by licensed, qualified and competent individuals or contracting companies.

Report Summary

This summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your real estate agent or an attorney.

Interior

1) The balancing spring has detached from the single hung window, located in the dining room - north side. Recommend repairing the window.



Figure 2-1



Figure 2-2

Bedrooms: Master Bedroom

2) The master bedroom patio door is out of alignment making it difficult to open and close. Recommend repairing / adjusting the door so that it fits squarely in the frame and will easily open, close and latch.



Figure 3-1

Bedrooms: Bedroom 4

3) The hanging light fixture at bedroom 4 did not work. Recommend repairing.




Figure 8-1

Bathrooms: Bathroom #4

4) The exhaust fan cover is coming loose from the ceiling at bathroom 4 (back bedroom on the south side). Recommend reattaching and securing the cover to the ceiling.



Figure 13-1

Kitchen

5) The RO Drinking Water Faucet is leaking. Recommend repairing.



Figure 16-1

HVAC: HVAC System #1

6) The north side furnace would not run. Recommend further evaluation and repairs as necessary by a qualified mechanical contractor.




Figure 25-1

Electrical

7) The exterior GFCI outlet, located to the left below the electrical panel, is not working. Recommend repairing or replacing the outlet.




Figure 31-1



Figure 31-2

8) The interior electrical outlet, located on the south dining room wall, is loose. Recommend securing the outlet to the wall and junction box.




Figure 33-1

9) The electrical ceiling box at the office is open with exposed wires. Recommend installing a blank cover plate over the junction box.



Figure 34-1

General

Property Type: Single Family

Stories: One Approximate Age: 3 Yrs Bedrooms/Baths: 4/4.5 Door Faces: West Furnished: Yes Occupied: Yes Weather: Sunny Temperature: Cool Soil Condition: Damp

Utilities On During Inspection: Electric Service, Gas Service, Water Service

People Present: Client, Client's Agent

Site

The condition of the vegetation, grading, drainage, driveways, patios, walkways, and retaining walls are inspected with respect to their effect on the condition of the building.

Site Grading / Drainage: Sloped Away From Structure

Condition: Satisfactory

Vegetation: Generally Maintained

Condition: Satisfactory

Retaining Walls: Not Present

Driveway: Pavers

Condition: Satisfactory

Walkways: Pavers

Condition: Satisfactory

Steps/Stoops/Porches: Pavers

Condition: Satisfactory

Patios/Decks: Pavers

Condition: Satisfactory

Exterior

The visible condition of exterior coverings, trim and entrances are inspected with respect to their effect on the condition of the building.

Exterior Wall Cladding Material: Stone, Brick

Condition: Satisfactory

Trim Material / Flashings: Wood, Metal

Condition: Satisfactory

Eaves, Soffits, Fascia: Wood

Condition: Satisfactory

Entry Door: Steel

Condition: Satisfactory

Exterior Doors: Sliding Glass, Wood, Wood / Glass

Condition: Satisfactory Unless Noted Otherwise

Railings: Metal

Condition: Satisfactory

GFCI Devices: Outlets

Condition: Satisfactory Unless Noted Otherwise

Receptacle Polarity / Grounding: Satisfactory

Garage

Garage Type: Attached
Garage Size: 2 Car + 1 Car
Door Opener: Chain Drive

Condition: Satisfactory

Opener Safety Photo Eyes: Tested

Condition: Satisfactory

Door Operator Safety Reverse: Reversed When Met With Resistance

Seperation Walls / Ceiling / Door: Observed Where Present

Condition: Satisfactory Where Visible

GFCI Devices: Outlets

Condition: Satisfactory

Receptacle Polarity / Grounding: Satisfactory

Roofing

The visible condition of the readily accessible and visible roof covering, flashings, skylights, chimneys and roof penetrations are inspected. The purpose of the inspection is to determine general condition, NOT to determine life expectancy. Roofing underlayment for concrete tiles roofs is not inspected. Contact a Licensed Roofing Contractor if you desire to have the underlayment Inspected and evaluated. There is no guarantee written, expressed or implied for roofs being free from leaks.

Inspection Method: From Ground Roof Covering Materials: Concrete Tile

Condition: Satisfactory Where Visible

Approximate Roof Age: 3 Yrs
Flashings / Penetrations: Metal

Condition: Satisfactory Where Visible

Sky Lights: Not Present
Chimney: Not Present
Drainage Systems / Gutters & Not Present

Downspouts:

Signs Of Leaks: None Observed
Abnormal Condensation On None Observed

Building Components:

Structure

The visible condition of the structural components are inspected. The determination of adequacy of structural components is beyond the scope of a home inspection.

Foundation Types: Post Tensioned Slab

Condition: Satisfactory Where Visible

Foundation Material: Poured Concrete

Floor Structure: Concrete Slab On Grade

Condition: Satisfactory Where Visible

Wall Structure: Wood Framed

Condition: Satisfactory Where Visible

Columns: Not Present Ceiling Structure: Trusses

Condition: Satisfactory Where Visible

(Structure continued)

Signs of Water Penetration: None Observed

Attic

Attic Entry Method: Garage Ceiling Hatch, Bedroom Closet Ceiling

Hatch

Attic Inspection Method: Walked On Service Platform

Access Restrictions: Limited Access, Limited Visibility, Concealed

Areas, Inaccessible Areas

Roof Structure: Wood Trusses

Condition: Satisfactory Where Visible

Roof Deck Material: Oriented Strand Board

Condition: Satisfactory Where Visible

Vent Risers: ABS

Condition: Satisfactory Where Visible

Primary Ceiling / Roof Insulation: Loose Fill Cellulose

Condition: Satisfactory Where Visible

Vapor Retarders In Unfinished Asphalt Paper

Spaces: Condition: Satisfactory Where Visible

Ventilation: Roof Vents

Condition: Satisfactory Where Visible

Interior

The interior inspection is limited to readily accessible areas that are not concealed by furnishings or stored items. A representative number of windows, doors, switches, lights and outlets are operated.

Floors: Tile

Condition: Satisfactory

Walls: Painted Drywall, Bead Board

Condition: Satisfactory

Ceilings: Painted Drywall

Condition: Satisfactory

Window Types: Single Hung, Fixed

Condition: Satisfactory Unless Noted Otherwise

Amerigo Property Inspections: 12825 S. 71st Street, Tempe, AZ 85284

Page 13 of 51

(Interior continued)

Window Materials: Vinyl Interior Door Materials: Wood

Condition: Satisfactory

Fireplace:

Steps / Stairways:

Railings/ Handrails / Guardrails:

Signs Of Leaks Or Moisture

Not Present

Not Present

Not Present

Not Present

Not Present

Intrusion:

Signs Of Abnormal Or Harmful None Observed

Condensation:



Comment 1: Interior.




Figure 1-1



Figure 1-2

(Interior continued)







Figure 1-4



Comment 2:

The balancing spring has detached from the single hung window, located in the dining room - north side. Recommend repairing the window.




Figure 2-1



Figure 2-2

Bedrooms

New Item: Not Present

Master Bedroom

Windows: Single Hung, Fixed

Condition: Satisfactory

Outlets: 3 Pronged

Condition: Satisfactory

Heat / Cooling Source: Ceiling Register

Condition: Satisfactory

Light: Recessed Loghts, Can Lights

Condition: Satisfactory



Comment 3:

The master bedroom patio door is out of alignment making it difficult to open and close. Recommend repairing / adjusting the door so that it fits squarely in the frame and will easily open, close and latch.



Figure 3-1

(Master Bedroom continued)



Comment 4: Master Bedroom.




Figure 4-1

Bedroom 2

Windows: Single Hung

Condition: Satisfactory

Outlets: 3 Pronged

Condition: Satisfactory

Heat / Cooling Source: Ceiling Register

Condition: Satisfactory

Light: Can Lights

Condition: Satisfactory

(Bedroom 2 continued)



Comment 5: Bedroom 2.



Figure 5-1

Bedroom 3

Windows: Single Hung

Condition: Satisfactory

Outlets: 3 Pronged

Condition: Satisfactory

Heat / Cooling Source: Ceiling Register

Condition: Satisfactory

Light: Can Lights

Condition: Satisfactory

(Bedroom 3 continued)



Comment 6: Bedroom 3.




Figure 6-1

Bedroom 4

Windows: Single Hung

Condition: Satisfactory

Outlets: 3 Pronged

Condition: Satisfactory

Heat / Cooling Source: Ceiling Register

Condition: Satisfactory

Light: Ceiling Light , Can Lights

Condition: Repair As Noted

(Bedroom 4 continued)



Comment 7: Bedroom 4.



Figure 7-1



Comment 8:

The hanging light fixture at bedroom 4 did not work. Recommend repairing.



Figure 8-1

(Bedrooms continued)

Bedroom 5

Windows: Single Hung

Condition: Satisfactory

Outlets: 3 Pronged

Condition: Satisfactory

Heat / Cooling Source: Ceiling Register

Condition: Satisfactory

Can Lights

Condition: Satisfactory



Comment 9: Bedroom 5.

Light:



Figure 9-1

Bathrooms

Master Bathroom

Location: Master Bedroom

Bath Tub / Fixtures: Recessed

Condition: Satisfactory

Shower / Fixtures: Stall

Condition: Satisfactory

Sink(s) / Faucet(s): Double Vanity

Condition: Satisfactory

Toilet: Standard Tank

Condition: Satisfactory

Shower Walls: Tile

Condition: Satisfactory

Tub Surround: Tile

Condition: Satisfactory

Floor: Tile

Condition: Satisfactory

Ventilation Type: Ventilator, Window

Condition: Satisfactory

GFCI Devices: Not Present Receptacle Grounding / Polarity: Satisfactory

Leaks: None Observed

Bathroom #2

Location: Bedrooms 2/3

Bath Tub / Fixtures: Recessed

Condition: Satisfactory

Shower / Fixtures: In Tub

Condition: Satisfactory

Sink(s) / Faucet(s): Double Vanity

Condition: Satisfactory

Toilet: Standard Tank

Condition: Satisfactory

(Bathroom #2 continued)

Shower Walls: Tile

Condition: Satisfactory

Tub Surround: Tile

Condition: Satisfactory

Tile Floor:

Condition: Satisfactory

Ventilator Ventilation Type:

Condition: Satisfactory

GFCI Devices: Not Present Satisfactory Receptacle Polarity / Grounding: Leaks:

None Observed



Comment 10: Jack And Jill Bathroom.



Figure 10-1



Figure 10-2

(Bathrooms continued)

Bathroom #3

Location: Bedroom 4
Bath Tub / Fixtures: Recessed

Condition: Satisfactory

Shower / Fixtures: In Tub

Condition: Satisfactory

Sink(s) / Faucet(s): Single Vanity

Condition: Satisfactory

Toilet: Standard Tank

Condition: Satisfactory

Shower Walls: Tile

Condition: Satisfactory

Tub Surround: Tile

Condition: Satisfactory

Floor: Tile

Condition: Satisfactory

Ventilation Type: Ventilator

Condition: Satisfactory

GFCI Devices:

Receptacle Polarity / Grounding:

Leaks:

Not Present

Satisfactory

None Observed

(Bathroom #3 continued)



Comment 11: Bathroom 3 at Bedroom 4.



Figure 11-1

Bathroom #4

Location: Bedroom 5
Bath Tub / Fixtures: Recessed

Condition: Satisfactory

Shower / Fixtures: In Tub

Condition: Satisfactory

Sink(s) / Faucet(s): Single Vanity

Condition: Satisfactory

Toilet: Standard Tank

Condition: Satisfactory

Shower Walls: Tile

Condition: Satisfactory

Tub Surround: Tile

Condition: Satisfactory

Floor: Tile

Condition: Satisfactory

(Bathroom #4 continued)

Ventilation Type: Ventilator

Condition: Repair As Noted

GFCI Devices: Outlets

Condition: Satisfactory

Receptacle Polarity / Grounding: Satisfactory

Leaks: None Observed



Comment 12: Bathroom 4 at Bedroom 5.



Figure 12-1



Comment 13:

The exhaust fan cover is coming loose from the ceiling at bathroom 4 (back bedroom on the south side). Recommend reattaching and securing the cover to the ceiling.

(Bathroom #4 continued)



Figure 13-1

Powder Room

Location: **Bedroom Hallway**

Sink(s) / Faucet(s): Pedestal

Condition: Satisfactory

Toilet: Standard Tank

Condition: Satisfactory

Tile Floor:

Condition: Satisfactory

Ventilation Type: Ventilator

Condition: Satisfactory

GFCI Devices: Receptacle Polarity / Grounding:

Satisfactory

Not Present

Leaks:

None Observed

(Powder Room continued)



Comment 14: Powder Room.



Figure 14-1

Kitchen

Cabinets: Wood, Laminated

Condition: Satisfactory

Countertops: Quartz

Condition: Satisfactory

Sink / Fixtures: Single

Condition: Satisfactory

GFCI Devices: Not Present Receptacle Polarity / Grounding: Satisfactory

Kitchen / Stove / Cooktop Exhausted Hood

Ventilation : Condition: Satisfactory

Leaks: None Observed

(Kitchen continued)



Comment 15: Kitchen.






Figure 15-1

Figure 15-2



Comment 16:

The RO Drinking Water Faucet is leaking. Recommend repairing.



Figure 16-1

(Kitchen continued)

Appliances

This is a cursory check only of the specified appliances. The accuracy or operation of timers, temperature or power level controls is beyond the scope of this inspection.

Oven: Kitchen Aid

Condition: Operated

Cooktop: Kitchen Aid

Condition: Operated

Range Hood: Kitchen Aid

Condition: Operated

Refrigerator: Kitchen Aid

Condition: Operated

Dishwasher: Kitchen Aid

Condition: Operated

Microwave: Kitchen Aid

Condition: Operated

Disposal: Badger

Condition: Operated

Laundry

Clothes washers and dryers will not be moved to inspect plumbing or electrical connections. Buyers should inspect each of these connections during the final walk through and while moving in. Clothes Dryer exhaust pipes should be routinely cleaned and inspected by qualified professionals. It is recommended that Buyers clean and inspect the clothes dryer exhaust duct prior to use.

Built In Cabinets: Yes

Condition: Satisfactory

Laundry Sink / Faucet: Yes

Condition: Satisfactory

Dryer Venting: To Exterior

Condition: Satisfactory Where Visible

Page 30 of 51

(Laundry continued)

Clothes Washer Connections: Cold Water Supply, Hot Water Supply, Drain, Electric

Outlet

Condition: Satisfactory

Clothes Dryer Connections: Electric

Condition: Satisfactory

Washer:

Dryer:

GFCI Devices:

Polarity / Grounding:

Not Inspected
Not Inspected
Not Present
Satisfactory

Room Ventilation: Window, Electric Fan

Condition: Satisfactory

Leaks: None Observed



Comment 17:

Laundry Room - the washing machine water supply valves are visually inspected when visible but are not operated. Dryer exhaust pipes should be routinely cleaned.



Figure 17-1

Plumbing

The plumbing system is inspected visually and by operating all fixtures, including their faucets, water closet flush valves, and all exterior hose faucets including only those that are attached to the house. Most of the water and waste distribution systems are concealed in walls and below the ground and cannot be seen. Functional Flow will be evaluated and reported as Satisfactory when a reasonable flow occurs while operating the highest fixture in the dwelling and simultaneously operating a second fixture. Functional Drainage will be evaluated and reported as Satisfactory when a drain empties in a reasonable amount of time and does not overflow when another fixture is drained simultaneously. Clients should hire qualified plumbers to camera the waste lines on homes built prior to 1975. Private water and waste systems are beyond the scope of a home inspection. This inspection does not include determining the effectiveness of anti-siphon devices, inspecting water conditioning systems, inspecting fire and lawn sprinkler systems, and evaluating water quality.

Location of Main Water Shutoff: Front - South Side

Water Supply System / Pipe Copper, PEX

Materials: Condition: Satisfactory Where Visible

Water Supply Pipe Supports And Observed Where Visible

Insulation: Condition: Satisfactory Where Visible

Functional Flow: Adequate

Leaks At Water Supplies: None Observed
Cross Connections: Dishwasher Drain

Condition: Satisfactory

Waste, Drain & Vent Pipe Systems: ABS Plastic

Condition: Satisfactory Where Visible

Drain Pipe Supports: Observed Where Visible

Condition: Satisfactory Where Visible

Functional Drainage: Adequate

Leaks At Drain / Waste Lines: None Observed

Location of Fuel Shutoff: At Meter
Fuel Storage Systems: Not Present
Fuel Distribution Systems / Black Iron Pipe

Supports: Condition: Satisfactory Where Visible

Fuel System Leaks: None Observed Sump Pump: Not Present

(Plumbing continued)



Comment 18: Water Service.



Figure 18-1



Comment 19: Gas Service.



Figure 19-1

(Plumbing continued)

Refrigerators and clothes washers will not be moved to inspect water supply lines. Buyer should inspect these water supplies during the final walk through and or while moving into the home. Any adverse conditions, including leaks, should be corrected immediately by a qualified plumber.

Water Heater

Water Heating System: Gas Water Heater

Condition: Satisfactory

Manufacturer: Bradford White

Operating Controls: Thermostatic Controller

Condition: Satisfactory

Fuel: Natural Gas

Capacity: 50 gal Approximate Age: 3 Yrs

Temp & Pressure Relief Valve: Present With Blow Off Leg

Condition: Satisfactory Where Visible

Automatic Safety Controls: Observed Where Visible

Condition: Satisfactory Where Visible

Fuel Disconnect: In Same Room

Condition: Satisfactory

Chimneys, Flues, Vents: Metal

Condition: Satisfactory Where Visible

Room Ventilation: High / Low Louvered Vents

Condition: Satisfactory

(Water Heater continued)



Comment 20: Water Heater.



Figure 20-1




Figure 20-2

HVAC

The air conditioning system(s) is inspected visually and operated by normal controls to determine general condition NOT life expectancy. The capacity or adequacy of the air conditioning system is beyond the scope of a home inspection. Buyers should hire licensed HVAC contractors to inspect and evaluate the systems if more information is desired that is beyond the scope of this inspection.

Presence Of A Heat Source In Each Yes

Room:

Presence Of A Cooling Source In Yes

Each Room:

Filter(s): Disposable

Condition: Satisfactory

(HVAC continued)

HVAC System #1

Location: North Side System

Type of Equipment: Split Cooling System with Furnace

Condition: Repair or Replace

Operating Controls: Thermostat

Condition: Repair or Replace

Automatic Safety Controls: Observed When Present & Visible

Condition: Satisfactory Where Visible

Manufacturer: Carrier Approximate Age: 3 Yrs

Heating Fuel: Natural Gas

Chimneys, Flues, Vents: PVC

Condition: Satisfactory

Distribution Systems: Flexible Ducting

Condition: Satisfactory Where Visible



Comment 21:

Thermostat at the Living Room.



Figure 21-1



Comment 22:

Thermostat at the Master Bedroom.



Figure 22-1



Comment 23: North Side - AC Equipment .



Figure 23-1




Figure 23-2



Figure 23-3



Comment 24:

Cooling Mode Split-

Return Air Temperature: 66 degrees Supply Air Temperature: 46 degrees

Split / Temperature Differential: 20 degrees .



Figure 24-1



Figure 24-2



Comment 25:

The north side furnace would not run. Recommend further evaluation and repairs as necessary by a qualified mechanical contractor.




Figure 25-1

Air conditioning systems should be checked, cleaned and serviced yearly by a licensed contractor.

HVAC System #2

Location: South Side System

Type of Equipment: Split Cooling System With Furnace

Condition: Satisfactory

Operating Controls: Thermostat

Condition: Satisfactory

Automatic Safety Controls: Observed When Present & Visible

Condition: Satisfactory Where Visible

Manufacturer: Carrier Approximate Age: 3 Yrs

Heating Fuel: Natural Gas

Chimneys, Flues, Vents: PVC

Condition: Satisfactory

Distribution Systems: Flexible Ducting

Condition: Satisfactory Where Visible



Comment 26:

Thermostat at the South Bedroom Hallway.



Figure 26-1



Comment 27:

Heat Mode Split-

Return Air Temperature: 70 degrees Supply Air Temperature: 117 degrees

Split / Temperature Differential: 47 degrees .



Figure 27-1



Figure 27-2



Comment 28: South Side - AC Equipment.



Figure 28-1



Figure 28-2



Figure 28-3



Comment 29:

Cooling Mode Split-

Return Air Temperature: 69 degrees Supply Air Temperature: 48 degrees

Split / Temperature Differential: 21 degrees .



Figure 29-1



Figure 29-2

Air conditioning systems should be checked, cleaned and serviced yearly by a licensed contractor.

Electrical

There are limitations to inspecting the Electrical System. Many electrical components are concealed and not visible. The inspection is mostly visual with the exception of operating a representative numbers of light fixtures, switches, and outlets. The only testing equipment used is an outlet tester. The inspection does not include operating any overcurrent device except for ground fault interrupters, low voltage systems, smoke detectors, telephone systems, security systems, and TV systems.

Type of Service: Underground

Condition: Satisfactory

Main Disconnect: At Service Panel

Condition: Satisfactory

Service Panel Location: Exterior
Service Panel Manufacturer: Square D

Condition: Satisfactory

Service Entrance Conductors: Unknown - Not Visible

Condition: No Visible Indication Of Damage

Service Voltage: 240 volts Service Amperage: 200 amps Service Panel Ground: Gas Pipe

Condition: Satisfactory

Branch Circuit Wiring: Solid Copper, Stranded Copper, Stranded Aluminum

Condition: Satisfactory Where Visible

Conductor / Breaker Compatibility : No Visible Indication Of Incompatibility

Overcurrent Protection: Breakers

Condition: Satisfactory

GFCI/AFCI Breakers: GFCI

Condition: Satisfactory

Lights & Switches: Operated

Condition: Satisfactory Unless Noted Otherwise

Outlets: Operated

Condition: Satisfactory Unless Noted Otherwise

Smoke Detectors: Present

Condition: Recommend Testing Weekly



Comment 30: Electrical Service Panel.



Figure 30-1



Figure 30-2



Comment 31:

The exterior GFCI outlet, located to the left below the electrical panel, is not working. Recommend repairing or replacing the outlet.



Figure 31-1



Figure 31-2



Comment 32: Distribution Panel - single car garage.



Figure 32-1




Figure 32-2



Comment 33:

The interior electrical outlet, located on the south dining room wall, is loose. Recommend securing the outlet to the wall and junction box.



Figure 33-1



Comment 34:

The electrical ceiling box at the office is open with exposed wires. Recommend installing a blank cover plate over the junction box.



Figure 34-1

Pool/Spa

The inspection of the pool/spa and related components is limited to the visual observation of the listed components if operating. The determination of if the pool is leaking or will leak is beyond the scope of this inspection.

Pool / Spa Type: In Ground Pool

Water Clarity: Clear Decking / Coping Material: Pavers

Condition: Satisfactory

Interior Finish / Steps: Concrete/Aggregate

Condition: Satisfactory

Installed Equipment: Pump Motor was turned on and appears to function no

warrantee is implied regarding condition of motor,

Cartridge Filter, Gauges, Piping, Valves

Condition: Satisfactory Unless Noted Otherwise

Type of Barrier: Fence, Wall

Condition: Further Evaluation Required

Electrical Equipment: Pool Light, GFCI, Timer, Conduits, Bonding

Condition: Satisfactory Where Visible

(Pool/Spa continued)

Heater: Not Present
Heater Safety Controls: Not Present
Cleaning System: In Floor

Condition: Satisfactory

Drain Covers: Anti-Entrapment Type

Condition: Satisfactory

Handrails / Ladders: Not Present Cross Connections: Pool Filler

Condition: Satisfactory



Comment 35:

Pool.



Figure 35-1

(Pool/Spa continued)



Comment 36:

The pool light worked and is GFCI protected.



Figure 36-1



Comment 37: Cartridge Filter.



Figure 37-1



Figure 37-2

(Pool/Spa continued)



Comment 38:

The water feature operated.



Figure 38-1



Comment 39:

The pool barrier may or may not meet all pool barrier requirements and regulations. Barrier regulations have specific requirements for closing, latching and locking doors, windows and gates that lead into the pool area. Often there are multiple options for compliance. Buyer should investigate all requirements with local governing agencies and make repairs as necessary.

4444 E. Mendocino Dr., Chandler, AZ 85286

The listed components and systems that are required to be observed per the Standards of Professional Practice, Sections 4-12, have been observed where visible and readily accessible. In the event a condition for each of the listed items has not been noted elsewhere in this report, the condition is Satisfactory. If the Client has any questions regarding a listed system or component and feels the report does not provide adequate information regarding the condition please contact the company or inspector. The company and inspector have the right to amend, update and or modify the report as might be deemed necessary.